

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
Airbus				
A300-600				
	EASA.A.S.00387	EASA.A.S.00387	Airbus Deutsland GmbH	MD Cargo System
	SA3483NM		Rockwell Collins	Installation of Trans Com video projection system.
	ST00526W1-D (Airbus)		Rockwell Collins	Modification of Collins VHF-700/VHF-700A/VHF-900-VHF COMM Receiver Transmitter Installation to a Collins VHF-700B/VHF-900B COMM Receiver
	ST01223AT-D		TIMCO	Inst.Airshow 210 syst.pdf
A310-300				
	SA3428NM		Rockwell Collins	Installation of an Asinc Airshow 100 Passenger Information System in accordance with FAA approved As
	SA5814NM		ACSS	Installation of Honeywell traffic alert and collision avoidance system.
	ST00100NY		EADS Airbus GmbH	Conversion of Passenger to Freighter configuration by installing a large Main Deck Cargo door, upper deck class E cargo compartment, floor reinforcement, and other associated modifications. For some models, only specific serial numbered aircraft apply.
	ST116-03NM		Air France	Cabin Conversion of A310 Austrian Airlines Cabin Conversion into a 196 Pax. 2 class Version Cabin Conversion Lavatory Modification"
Boeing Co.				
B737-300				
	SA2968SO		Pemco Aeroplex, inc.	Modification of floor.
	SA2969SO		Pemco Aeroplex, inc.	Installation of a cargo door.
	SA2970SO		Pemco Aeroplex, inc.	Installation of a Class E cargo compartment and passenger interior configuration.
	SA2971SO		Pemco Aeroplex, inc.	Installation of a cargo loading system.
	SA3169SO		General Aerospace, Inc	Installation of a Collins TPR-720 Mode S Transponder and a Honeywell Traffic Alert and Collision Avo
	SA3441NM		International Value	Installation of Floor Proximity Emergency Escape Path Marking System.
	SA3498NM		Smiths Aerospace	Installation of Smiths Industries fuel quantity gauge system.
	SA4978NM		Tramco	Installation of traffic alert and collision avoidance system (TCAS) provisions.
	SA5530NM		ACSS	Installation of Honeywell traffic alert and collision avoidance system(TCAS II).

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	ST00137AT		Rockwell Collins	Installation of a Collins TCAS II system.
	ST00146AT		Pemco Aeroplex, inc.	Installation of a second HF radio system.
	ST00389SE		Honeywell International	Installation of the Honeywell Enhanced Ground Proximity Warning System per Master Drawing 960-2227-0
	ST00525WI-D		Rockwell Collins	Modification of Collins 618M-4 VHF COMM Receiver Transmitter Installation to a 618M-5 VHF COMM Receiver Transmitter installation with either a Gables G7406-02 or Avtech 7522-1-2 VHF COMM Receiver Transmitter
	ST00526W1-D		Rockwell Collins	VHF 8,33 Khz.Ch. Spacing
	ST00717WI		Honeywell International	Installation of AlliedSignal Mark II Communications Management Unit (CMU) and Multi-Input Interactive Display Unit (MIDU) as per AlliedSignal Master Drawing List for no. 159-08189-0001 Rev E dtd 8/30/00, FAA approved 10/2/00 or later.
	ST00740LA-D		Hollingshead International	Installation of smoke detection and fire suppression systems provisions, lower cargo compartments.
	ST00847SE		Smiths Aerospace	Installation of Model 4035 Transient Suppression Units on Boeing 737 Classic Airplanes fitted with Smiths Digital Fuel Gauging Systems. Responsible ACO is Seattle ACO.
	ST00939SE		Honeywell International	Inst. DFDAU Solid State Acc.Unit
	ST01060CH		Electronic Cable Specialists	Installation of Dual GPS Antenna and Cox Cable.
	ST01143SE		Jamco America, Inc.	Installation of a new security flight deck door in accordance with JAMCO America Master Drawing List (MDL) No. IA-085COAMD, Revision C, dated, November 6, 2002, or later FAA approved revision.
	ST01335LA		C & D Interiors	Installation of a reinforced cockpit door.
	ST01371AT		Pemco Aeroplex, inc.	Installation of overhead bins. (737-300 SERIES S/N 24021)
	ST01536LA		Ancra International LCC	ST01536LA
	ST01556LA		mMeggitt Safety Systems	Installation of high temperature, semi-rigid, coaxial fire/overheat detection wire harness cable ass
	ST01583LA		ACSS	Inst. T2CAS
	ST01798CH		Electronic Cable Specialists	Installation of a Honeywell Enhanced Ground Proximity Warning System per Electronic Cable Specialists Master Data List ECS-201532 latest FAA approved revision.
	ST02008AT		General Aerospace, Inc	Installation of AlliedSignal 18 Channel Digital Flight Data Recorder (Upgrade).
	ST02472AT		Avionics Support Group	Installation of a mini Quick Access Recorder (QAR).
	ST02716AT		EMTEQ Engineering	Installation of Honeywell Ground Proximity Warning System.

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	ST02723AT		EMTEQ Engineering	Installation of EMTEQ Engineering dual GPS antenna provisions in accordance with Avitas Engineering
B737-400				
	SA00860LA		Hollingscad International,	Inst. Enhanced VHF Radio Gables
	SA3498NM		Smiths Aerospace	Installation of Smiths Industries fuel quantity gauge system.
	SA3992NM		Rogerson ATS	Inst. 500 Gallon Aux Fuel tank
	SA5185NM		Tramco	Inst. Dual mode-S ATC
	SA5530NM		ACSS	Installation of Honeywell traffic alert and collision avoidance system(TCAS II).
	SA8030NM		Teledyne Controls	Installation of Teledyne Controls digital flight data acquisition unit (DFDAU) and digital flight data management unit (DFDMU).
	ST00127BO		Simmonds Precision	Digi. Fuel Qty. Ind // FQIS Transient Suppress Dev
	ST00389SE		Honeywell International	Installation of the Honeywell Enhanced Ground Proximity Warning System per Master Drawing 960-2227-0
	ST00525WI-D		Rockwell Collins	Modification of Collins 618M-4 VHF COMM Receiver Transmitter Installation to a 618M-5 VHF COMM Receiver Transmitter installation with either a Gables G7406-02 or Avtech 7522-1-2 VHF COMM Receiver Transmitter
	ST00526WI-D		Rockwell Collins	Modification of Collins VHF-700/VHF-700A/VHF-900-VHF COMM Receiver Transmitter Installation to a Col
	ST00782SE		Britax Heath Tecna Inc.	Inst. ATIX2 Retrofit kit
	ST00847SE		Smiths Aerospace	Installation of Model 4035 Transient Suppression Units on Boeing 737 Classic Airplanes fitted with Smiths Digital Fuel Gauging Systems. Responsible ACO is Seattle ACO.
	ST00899AT		Honeywell International	Installation of CAS-81 TCAS system.
	ST00939SE		Honeywell International	Inst. DFDAU Solid State Acc.Unit
	ST00971SE-D		Goodrich Aviation	Inst. Cockpit Door surveillance system
	ST01060CH		Electronic Cable Specialists	Installation of Dual GPS Antenna and Cox Cable.
	ST01187CH		EAD Inc.	Installation of an AlliedSignal CAS 81 traffic alert and collision avoidance system (TCAS
	ST01198SE		Flight Structures, Inc.	Reconfig. To 170 Pax
	ST01335LA		C & D Interiors	Installation of a reinforced cockpit door.
	ST01583LA		ACSS	Inst. T2CAS
	ST01829AT		SAF-T-GLO	Installation of SAF-T-GLO Aerospace Limited's photoluminescent floor proximity emergency escape path

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	ST02472AT		Avionics Support Group	Installation of a mini Quick Access Recorder (QAR).
	STO1829AT		Diversified Aviation	SAF-T-GLO
B747-200	AAN17504		British Airways	FMC Retrofit Program
	AAN22213		British Airways	Introduction of ARINC Communication Addressing
	AAN22239		British Airways	TCAS II Installation
	AAN23501		British Airways	Entertainment System Installation
	AAN24797		British Airways	GPWS-Installation of MK VII Computer
	AAN24798		British Airways	Omnibus Modification
	AAN25020		British Airways	Omnibus Modification, incl. Sidewall and Overhead bin extension.
	AAN25225		British Airways	Omnibus Modification
	AAN26845		British Airways	Installation of a Predictive Windshear System
	SA1220NW		Allied Signal	Instl. Of Universal Flight Data Recorder
	SA2329SO		Aeronautical Engineers,	Installation of Galley in Upper Deck
	SA2365NM		Hexcel Corporation	SuperBin Interior Retrofit
	SA2420NM		Rockwell Collins	Trans Video Com Projection
	SA3122SO		Bendix/King	Bendix/King CAS-81 TCAS II and dual TRA-67 Mode S Transponder Installation.
	SA3748NM		Litton Systems, Inc.	Installation of 3 Litton LTN-92 Inertial Navigation System (INS)
	SA4885NM		Honeywell International	TCAS 2000 CHANGE 7 Honeywell TCAS II Installation
	SA5014NM		Ancra International LCC	Main Deck Cargo Sys. Electrical Installation
	SA5014NM/SA-58		IAI/Ancra International	Drawings List DL82000, RB EO 24758
	SA5057NM		Israel Aircraft Industries	Special Freighter Configuration
	SA5057NM/SA-58		Israel Aircraft Industries	Special Freighter Configuration
	SA5106NM		Allied Signal	Allied Signal GRND PROX/ WINSHR Warning
	SA5865NM		Aero Union Corp.	Manf/Instl. Cargo Transfer System
	ST00020B0		BF Goodrich Aerospace	INSTAL DIGITAL FUEL QUANTITY INDICATING SYSTEM (FQIS)
	ST00020B0		BF Goodrich Aerospace	Installation of Goodrich PN 300498 FQIS
	ST00053LA-D		Elsingore LP	GTE Airfone Digital Public Telephone System.

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	ST00112LA-D		Ancra International LCC	Lower Cargo compartment PDU installation
	ST00149LA		Ancra International LCC	Lower deck power drive installation
	ST00181SE		Smith Industries	Installation of Smiths Transient Suppression Unit
	ST00214SE		Flight Structures, Inc.	Design change from combined pass/freighter to full freighter
	ST00273AT		TIMCO	Airshow 210 Entertainment System
	ST00353SE		LiteAir Aviation Products	Installation of Light weight Windows Plug
	ST00358LA		Israel Aircraft Industries	
	ST00380SE		Becontree Holdings	To increase Maximum and Zero Fuel Weights
	ST00405SE		Hexcel Corporation	Centerline Bins
	ST00483WI		B&D Instr. & Avionics,	Component Mod EGT Indicator Repl. Replaced by Penny & Giles
	ST00504AT		Rockwell Collins	Collins SAT -906 SATCOM System
	ST00504LA		Litton Systems, Inc.	LTN-92 Inertial Navigation Sys mod
	ST00525WI-D		Rockwell Collins	Modification of Collins 618M-4 VHF COMM Receiver Transmitter Installation to a 618M-5 VHF COMM Receiver Transmitter installation with either a Gables G7406-02 or Avtech 7522-1-2 VHF COMM Receiver Transmitter
	ST00634LA		ARINC, INC	Installation of IIMorrow Navigation System, with Global Positioning System.
	ST00674AT		Rockwell Collins	GEC MARCONI AD 5100 Airborne Telephone System
	ST00675CH		ERDA Inc.	Installation of Crew Bunk
	ST00705SE		Allied Signal	Installation of the Allied Signal MK VII Enhanced GPWS
	ST00714LA		Litton Systems, Inc.	Installation of triple Litton INS with RNAV updating.
	ST00836LA		ARINC, INC	Upgrade of existing Communication Equipments.
	ST00949CH		AAR Cargo System	Cargo Handling System
	ST00956AT		Allied Signal	Mark II ACARS installation
	ST01008SE		Flight Structures, Inc.	Upper deck Mod.
	ST01320AT		E.J.Mlynartzyk & Co Inc.	Matsushita System 2000E Passenger Entertainment System
	ST01429CH		Spirent / Canardaero	Performance computer docking station
	ST01702LA		ACSS	Installation of Traffic Collision and avoidance System (TCAS) II and Terrain Awareness and Warning System
	ST020BO		BF Goodrich Aerospace	Computerized fuel Quantity Indication Sys Repl.

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	ST02472AT		Avionics Support Group	Installation of a mini Quick Access Recorder (QAR).
	ST02900AT		Avionics Support Group	Installation of provisions for the installation of ACSS T2CAS
	ST04272AT		Avionics Support Group	INSTALLATION OF MINI QAR
	ST0472AT-T		Avionics Support Group	Installation of Mini QAR
	ST05106NM		Honeywell International	MK VII Windshear Warning System
	ST0666CH		AAR Cargo System	CARGO HANDLING SYSTEM INSTALLATION
	TA0023		Lufthansa Technik	TCAS and ATC Mode S Transponder
	TA0143		Lufthansa Technik	Fuel Quantity Indicating System Retrofit
	TA0239		Allied Signal	Installation of the Allied Signal MK VII Enhanced GPWS
	TA0283		Lufthansa Technik	TCAS-Upgrade to SW Version 7.0
	TA0309		Lufthansa Technik	Installation of Quick Donning Masks
B747-300				
	EASA.A.S. 00282	EASA.A.S. 00282	ATS International	MARK VII EGPWS Installation
	IM29-SF-0221		Madelec Aero.	Photo Luminescent Path Installation
	IM29-SF-0269		EAD Inc.	Installation of FMS
	IM29-SF-0284		Corsair International	Individual Distribution Video System Installation
	IM29-SF-0285		Corsair International	Upper Deck, 16 retractable Video Screen Installation
	IM29-SF-0286		Corsair International	Economic Class Video System Modification
	IM29-SF-0287		Corsair International	APAX 120 Rockwell Collins Multiplex
	IM29-SF-0288		Corsair International	Cabin Reconfiguration to 25B-555Y version
	IM29-SF-0289		Corsair International	Installation of Center Beam and Ha-Racks in zone B
	IM29-SF-0290		Corsair International	Installation and Modification of seats crown section and galley hard points A
	SA2636CE		Rockwell Collins	Install Dual Collins TPR-720 Mode S Transponder
	SA3050SO		Honeywell International	Installation of CAS-81 TCAS
	SA3051SO		Honeywell International	Installation of ATC Mode S
	SA3122SO		Bendix/King	Bendix/King CAS-81 TCAS II and dual TRA-67 Mode S Transponder Installation.
	SA3943NM		C & D Interiors	Installation of C&D Interiors Outboard Bins and Sidewall Panels, Stowage Unit, Class Divider, Super Bin Kit

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	SA4885NM		Honeywell International	TCAS 2000 CHANGE 7 Honeywell TCAS II Installation
	SA5106NM		Allied Signal	Allied Signal GRND PROX/ WINSHR Warning
	SA5124NM		Flight Structures, Inc.	M/D arrangement including Bucher Galleys, PSU's, Seats and ACARS.
	SA6002NM		Teledyne Controls	Install OQAR
	ST00020BO		BF Goodrich Aerospace	Installation of Goodrich PN 300498 FQIS
	ST00084WI		B&D Instr. & Avionics,	Replacement of Exhaust Gas Temperature Indicators
	ST00182LA		Honeywell International	Satcom Installation
	ST00525WI-D		Rockwell Collins	Modification of Collins 618M-4 VHF COMM Receiver Transmitter Installation to a 618M-5 VHF COMM Receiver Transmitter installation with either a Gables G7406-02 or Avtech 7522-1-2 VHF COMM Receiver Transmitter
	ST00705SE		Allied Signal	Installation of the Allied Signal MK VII Enhanced GPWS
	ST00846SE		Butler National	Installation of Transient Suppression Devices
	ST01702LA		ACSS	Installation of Traffic Collision and avoidance System (TCAS) II and Terrain Awareness and Warning System
	ST01770AT		Allied Signal	Installation of RTA-83A VHF Com System 8.33
	ST02900AT		Avionics Support Group	Installation of provisions for the installation of ACSS T2CAS
	ST0472AT-T		Avionics Support Group	Installation of Mini QAR
B747-400	SA5099NM		TIMCO	Installation of Asinc Airshow 200 passenger video information system.
	SA5473NM		Honeywell International	Installation of Racal Aeronautical satellite telephone communications(Satfone) system.
	SA5522NM		Thales	Installation of passenger video entertainment system.
	SA5658NM		Flight Structures, Inc.	Interior arrangement that includes repositioning a galley.
	SA5760NM		Flight Structures, Inc.	Installation of Flight Structures, Inc. Satcom provisions.
	SA7094NM		Rockwell Collins	Installation of Video Entertainment System.
	SA9046NM-D		Be Avionics	MODIFICATION OF BUSINESS AND FIRST SEATS FOR MAS HANDSET
	ST00125AT		Honeywell International	Installation of the CAS-81 TCAS II system.
	ST00167SE		Jamco America, Inc.	Installation of overhead storage bins.
	ST00182SE		Jamco America, Inc.	Installation of a dry galley unit.
	ST00184SE		Flight Structures, Inc.	Modification of Galley G2 unit and installation of a rice cooker/warmer. (747-412)

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	ST00565SE		Jamco America, Inc.	Installation of an interior modification in Zone B and Upper Deck
	ST00566AT		BFE Services	Installation of closets.
	ST00601LA-D		Primex Aerospace	Installation of Primex Empower System, Personal Electronic Device Power Supply.
	ST00618LA		Monogram Systems	Installation of Weber privacy dividers p/ns 872181-401 and 872182-401 through -407
	ST00638AT		Collins Aviation Service	Installation of Collins data link ACARS.
	ST00736AT		EJM Aerospace Services	Installation of a Matsushita Avionics System Corporation 2000E Audio/Video On-Demand Passenger Entertainment System.
	ST01194SE		Jamco America, Inc.	Installation of a new security flight deck door on Boeing 747-400 Series airplanes in accordance with JAMCO America, Inc., Master Drawing List (MDL)
	ST01331LA		Monogram Sanitation	Installation of trash compactor assembly.
	ST01681CH		Rosemount Aerospace Inc	Installation of Rosemount Aerospace cockpit door surveillance system (CDSS)
	ST01685AT		Honeywell International	Installation of the RTA-44D VHG Data Radio System and/or the RTA-83B VHF Communications System.
	ST01688AT		EJM Aerospace Services	Installation of a Matsushita MAS 2000E Audio/Video On Demand System.
	ST01689AT		Honeywell International	INSTALLATION OF MATSUSHITA 2000 AUDIO/VIDEO SYSTEM
	ST02673AT		Jamco America, Inc.	JAMCO AMERICA SB 747-25-M095 R3. SIA AMA:A4-171
B757-200	SA00381SE		Honeywell International	Installation of the AlliedSignal Enhanced Ground Proximity Warning System, P/N 965-0976-001-100-100
	SA3051SO		Honeywell International	Installation of ATC Mode S
	SA3475NM		Rockwell Collins	Installation of a Hughes-Avicom video entertainment system.
	SA4226NM-D		SBC-America, LLC	Installation of Scandinavian Bellyloading Co., sliding carpet loading system
	SA4723NY-T		ACSS	ModeS Elementary & Enhanced Modification to meet upcoming mandated.
	SA4839NM		ACSS	Installation of provisions for wiring and hardware for Honeywell Traffic Alert and Collision Avoidance System (TCAS II).
	ST00526WI-D		Rockwell Collins	Modification of Collins VHF-700/VHF-700A/VHF-900-VHF COMM Receiver Transmitter Installation to a Col
	ST00961AT		Honeywell International	Installation of a Flight Data Acquisition and Management System (FDAMS).
	ST01032SE		Honeywell International	Replacement of the Existing Tape Voice Recorder with a new Solid State Voice Recorder
	ST01334LA		C & D Aerospace	Installation of a reinforced cockpit door

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	ST01446LA		Hollingshead International	Intergrated Standby Flight Display (ISFD) System Installation
	ST01449CH		Electronic Cable Specialists	Installation of GPS antenna provisions.
	ST01839CH		Electronic Cable Specialists	Installation of a Honeywell Enhanced Ground Proximity Warning System.
	ST02221AT		SAF-T-GLO	Installation of SAF-TO-GLO photoluminescent floor proximity emergency escape with marking system (FPEEPMS).
	ST02472AT		Avionics Support Group	Installation of a mini Quick Access Recorder (QAR).
	ST8021AT-T		DER Services	AV-Sentinel GPS/Iridium Antenna Coaxial Cable Provision Installation
	TA0533		CTT	CTT System installation
B757-300				
	SA4723NY-T		ACSS	ModeS Elementary & Enhanced Modification to meet upcoming mandated.
	ST01334LA		C & D Aerospace	Installation of a reinforced cockpit door
	ST01446LA		Hollingshead International	Intergrated Standby Flight Display (ISFD) System Installation
B767-300				
	SA3433NM		Rockwell Collins	Installation of a Trans Com Video Projection system, Installaed by Boeing
	SA4195NM-D		Diressen Aircraft Interior	One coat closet, Two centerline class deviders, Four outboard class dividers, Two outboard closets and Four curtain track assembly
	SA5479NM		Rockwell Collins	Installation of In-Seat Video Entertainment System
	SA5520NM		Rockwell Collins	Installation of Asinc Airshow 200/210 Passenger Video Information System
	SA5541NM		ACSS	Installation of Honeywell traffic alert and collision avoidance system(TCAS II)
	SA5878NM		C & D Interiors	Installation of video control center
	SA5897NM		C & D Interiors	Installation of video control center P/N 6461001-103 (Cabinet only)
	SA6086NM		Honeywell International	Installation of Honeywell/Racal Aeronautical Satellite Communication System
	SA9006NM-D		C & D Interiors	Installation of Claircom Passenger Phone System
	ST00366LA		C & D Interiors	767-383er Block 1. Video Installation Changes in Conjunction With Reconfiguration From 41 to 47 inc Seat Pitch
	ST00417SE		Honeywell International	Installation of the Enhanced Ground Proximity Warning System
	ST00526WI-D		Rockwell Collins	Modification of Collins VHF-700/VIF700A/VHF-900 VIf COMM Receiver Transmitter Installation
	ST00678AT-D		Rockwell Collins	Installation of Collins DLM-700B Acars
	ST008009SE		Jamco America, Inc.	Installation of an interior modification

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	STO0809SE		Jamco America, Inc.	Installation of an interior modification
	STO0881WI-D		Rockwell Collins	Installation of Collins TCAS II change 7
	STO1282AT-D		Rockwell Collins	Installation of Collins DLM-900 Acars Management Unit
	STO1498AT-D		TIMCO	Installation of an Airshow 420 system
	STO2472AT		Avionics Support Group	Installation of a mini Quick Access Recorder (QAR).
	STO3038AT		Jossair Company	Installation of Cabin Interior Arrangement (261 pax)
	STO0204SE		Bucher Aerospace	Installation of service carts
	STO0205SE		Bucher Aerospace	Installation of service carts
	STO0206SE		Bucher Aerospace	Installation of service carts
	STO0393AT		Rockwell Collins	Installation of Collin TCAS 11
	STO0417SE		Honeywell International	EGPWS
	STO0526WI-D		Rockwell Collins	Modification of Collins VHF-700/VHF-700A/VHF-900 VHF comm. receivers to VHF700B/900B
	STO0885LA		Mass Systems Inc.	Installation of MASS System fire exting. cartridges. To replace Kidde and Pacific
	STO0952LA		Mass Systems Inc.	Installation of MASS System fire exting. cartridges. To replace Kidde and Pacific
	STO1298AT		Allied Signal	Installation of Allied Signal FDAMS with Mark 11 ACARS
	DC-9-82 (MD-82)			
	SA3969NM		Honeywell International	Installation of an electronic flight instrument system (EFIS).
	SA3970NM		Honeywell International	Installation of a flight management system (FMS).
	SA3971NM		Scandinavian Airlines	Installation of the Smiths Flat Panel Displays (EEDP, EOAP, ESDP) with Honeywell Thrust Rating Panel.
	STO1056LA		C & D Interiors	Installation of galleys, closet, stowage SIA, forward lavatory, bin, class divider (movable), sidewall and ceiling panels.
	STO1828AT		Honeywell International	Installation of RTA-83A VHF Communication System.
Cessna				
	140			
	SA13GL		Aircraft Wheel & Brake	Installation of Cleveland wheel No. 40-97A and brake No. 30-63A. (140A S/N 13400 AND UP)
	SA648NE		Stickley John E	Installation of Cessna 150 exhaust systems.

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
152	SA71GL		Brackett Aero Filters Inc.	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine aircraft.
	SE00979AT		Aircraft Specialties	Installation of a Teledyne Continental model O-200 crankshaft, connecting rods and
	SA71GL		Brackett Aero Filters Inc.	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine aircraft.
172	SA2375SW		RAM Aircraft	As modified per STC SE3692SW, install Lycoming O-320-D2G, O-320-D2J, or O-320-E2D engine rated for 160 hp take-off and 150 hp METO for models 172I, 172K, 172L, and 172M; or installation of Lycoming O-320-D2G, O-320-D2J, or O-320-E2D
	SE3692SW		RAM Aircraft	Increase 5 minute takeoff maximum power rating to 160 horsepower.
172M	SA02228AT		Power Flow Systems Inc	For model 172 airplanes with Lycoming O-360 engines per STC SA332GL or STC SA4428SW, modification of standard exhaust system. For model 172 with Lycoming O-360 engines per STC SA647CE or STC SA1324CE, modification of standard exhaust
	SA2196CE		Air Plains Services	Installation instructions for Gross Weight Increase.
172N	SA2375SW		RAM Aircraft	As modified per STC SE3692SW, install Lycoming O-320-D2G, O-320-D2J, or O-320-E2D engine rated for 160 hp take-off and 150 hp METO for models 172I, 172K, 172L, and 172M; or installation of Lycoming O-320-D2G, O-320-D2J, or O-320-E2D
	SA4428SW		Air Plains Services	Installation of 180 hp Lycoming O-360-A2F, -A3A and O-360-A4A, -A4M or -A4N engines and McCauley 1A170/CFA7660 propeller or Lycoming O-360-A4A, -A4M, -A4N engines and Sensenich76EM8S propellers.
	SA71GL		Brackett Aero Filters Inc.	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine aircraft.
	SA910CE		Horton STOL Craft	Installation of wing leading edge cuffs, drooped tips, stall fences and Aileron gap seals. (172, 172Q LANDPLANE) (172P LANDPLANE AND FLOATPLANE)
	SE3692SW		RAM Aircraft	Increase 5 minute takeoff maximum power rating to 160 horsepower.
	SE388NE		Cloutier Raymond R	Installation of Bendix magnetoes Model S4LN-21 and S4LN-20.
	SA2375SW		RAM Aircraft	As modified per STC SE3692SW, install Lycoming O-320-D2G, O-320-D2J, or O-320-E2D engine rated for 160 hp take-off and 150 hp METO for models 172I, 172K, 172L, and 172M; or installation of Lycoming O-320-D2G, O-320-D2J, or O-320-E2D
	SA703GL		Penn Yan Aero Service,	Installation of O-360-A4A, A4M, or A4N series engines and Sensenich76EM8SPY

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	SA71GL		Brackett Aero Filters Inc.	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine aircraft.
180	SE3692SW		RAM Aircraft	Increase 5 minute takeoff maximum power rating to 160 horsepower.
	SA01120SE		AP Enterprises LLC	Installation of Door Steward.
	SA1101GL		Shadin Company, Inc	Installation of a Shadin Co. fuel flow indicating system.
	SA334SW		InterAv, Inc	Installation of InterAv Alternator.
	SA71GL		Brackett Aero Filters Inc.	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine aircraft.
	SA967CE		Horton STOL Craft	STOL kit installation (wing leading edge cuffs, drooped tips, stall fences and aileron gap seals).
185F	SA01015SE		Alaskan Bushwheel Inc.	Installation of eligible Alaska Tire and Rubber Company TSO-C62d Tires as listed in Approved Model L
	SA2272CE		Air Plains Services	Installation of fuel reservoir(accumulator) quick drain. (A185F THRU S/N 18503153)
	SA3531NM		Bogert Aviation	Installing copper electrical cables. (182 S/N 33000 THRU 33842) (8E 833 and UP)
	SA3812NM		BAS	Installation of a BAS tail pull handle in the aft fuselage.
	SA3813NM		BAS	Installation of a BAS tail pull handle in the aft fuselage.
	SA63GL		Aircraft Wheel & Brake	Install Cleveland wheel and brake conversion kit, P/N 199-62.
	SR01543SE		Alaskan Bushwheel Inc.	The manufacture of an Alaskan Bushwheel tailwheel and fork assembly in accordance with Alaskan Buhwh
207A	SA1328CE		Horton STOL Craft	Installation of leading edge cuffs, droop tips, and staff fences.
	SA4605NM		Aero Twin	Installation of main gear gravel deflectors
FR-172J	SA2213CE		Horton STOL Craft	Install STOL kit.
P206	SA1939CE		Lanes Lebanon Air	Increase in gross weight from 3,300 lbs. to 3,600 lbs.
	SA71GL		Brackett Aero Filters Inc.	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine aircraft.

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
Piper				
<i>J-3C-65</i>				
	SA00073SE		Micro AeroDynamics, Inc	Installation of vortex generators to the wing upper surface at the leading edge.
	SA1516NM		Univair Aircraft Corp	Installation of stamped aluminum wing ribs.
	SA71GL		Brackett Aero Filters Inc.	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine aircraft.
	SA7435SW		Univair Aircraft Corp	Install Teledyne O-200A engine and McCauley 1A101-DCM propeller.
	SE00145WI		Bainbridge William C III	Installation of B&C Specialty Products Model BC 320-() Starter.
<i>PA-18-135</i>				
	SA00388NY		Cub Crafters, Inc	Installation of auxiliary baggage compartment.
	SA00703SE		Cub Crafters, Inc	Install right side access door.
	SA00951SE		Cub Crafters, Inc	Install headliner in accordance with Cub Crafters, Inc., Master Drawing List, MDL 105600, Rev. A, dated July 30, 2001, or later FAA approved revision.
	SA00997CH		Wipaire, Inc	Installation of gross weight increase Kit No. 10B1-6521, issued January 29, 1999.
	SA01015SE		Alaskan Bushwheel Inc.	Installation of eligible Alaska Tire and Rubber Company TSO-C62d Tires as listed in Approved Model L
	SA01026SE		Steves Aircraft	Installation of improved fuel gascolator. (Lationioame Ricana DE Aviacion (Lavia) S.A. PA-25 TC 2A8 and 2A10 - 150 hp model only.)
	SA01233SE		Alaskan Bushwheel Inc.	Manufacture of Alaskan Bushwheel, Inc. (ABI) tail wheel and fork assembly per ABI Document ABI-3200B, Revision A, dated April 28, 2005, or later FAA approved revision. The tail wheel and fork assembly must be installed in accordance with ABI
	SA02011AK		F Atlee Dodge Aircraft	Fabrication and installation of top deck assembly x-brace.
	SA02024AK		F Atlee Dodge Aircraft	Fabrication of F. Atlee Dodge part no. 3236 muffler shroud assembly.
	SA02043AK		F Atlee Dodge Aircraft	Fabrication and installation of pilot's seat belt attachment brackets.
	SA02138AK		Dans Aircraft Repair, Inc	Fabrication and installation of a light weight battery and bracket under the rear seat.
	SA02171AK		Dakota Cub Aircraft Inc	Installation of a 24-gallon right wing fuel tank, P/N DC18049-24G-25R and 24-gallon left wing fuel tank, P/N DC10849-24G-32L.
	SA02175AK		Budde Lee	Fabrication and installation of Airframes, Inc 3-inch extended main landing gear.
	SA11RM		Univair Aircraft Corp	Installation of modified axles, wheels and brakes. (J3C-65 Army L-4, L-4A, L-4B, L-4H, L-4J, Navy NE-1, NE-2)

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	SA1245CE SA17RM SA292AL		Cub Crafters, Inc Univair Aircraft Corp Ellis W T & Borer M R	Installation of Scott master cylinder with Flanagan Aircraft Company conversion. Replacement for Piper P/N 10033 landing gear vee. Increased gross weights to PA-18-150 weights and C.G. envelope. Note: Airplanes must have Lycoming O-320 engine installed except, the PA-18-135 or PA-18A-135 for which the engine change is optional.
	SA4535NM SA4615NM		Loewen Paul E F Atlee Dodge Aircraft	SA4535NM Fabrication and installation of welded steel universal aft fuselage float strut attachment fittings.
	SA4618NM SA4621NM SA554AL SA5948NM SA681AL SA92NW		F Atlee Dodge Aircraft F Atlee Dodge Aircraft Ronald E Sullivan Micro AeroDynamics, Inc F Atlee Dodge Aircraft Cub Crafters, Inc	Fabrication and installation of P/N 3166-1 main landing gear cabane vee assembly. Fabrication and installation of P/N 3164-1 main landing gear shock strut assemblies. Installation of third seat in baggage compartment. Installation of vortex generators on wing leading edge. Installation of removable crossbar. Installation of Lycoming O-360 series engine, McCauley1A200-FA8241 propeller, and associated sub-systems.
	PA-23-150 SA69SW SA71GL		Nayak Aviation Corp Brackett Aero Filters Inc.	Extended nose with baggage compartment. Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine aircraft.
	PA-23-250 SA01026SE SA1480WE SA3531NM SA4008NM SA693CE		Steves Aircraft Met-Co Aire Bogert Aviation Bogert Aviation Brackett Aero Filters Inc.	Installation of improved fuel gascolator. (Lationioame Ricana DE Aviacion (Lavia) S.A. PA-25 TC 2A8 and 2A10 - 150 hp model only.) Installation of an integral 24 gallon auxiliary fuel tank in each wing tip. Installing copper electrical cables. (182 S/N 33000 THRU 33842) (8E 833 and UP) Installation of removable panels on the battery box slides. Replace existing engine induction air filter with AC Spark Plug filter.
	PA-28-140B SA413CH SE367CH		Mattson Arthur R Mattson Arthur R	Installation of Lycoming engine Model O-320-D2A, O-320-D3G, or O-320-E2A (modified by STC SE367CH) Modification of engine by replacing four pistons with four O-320-D2A pistons.

Supplemental Type Certificate

Manufacturer	STC no.	EASA no.	Holder	Description
	<i>PA-28R-200</i> SA4528NM		Hartzell Propeller, Inc	Installation of a Hartzell HC-C3YR-1RF/F7282, constant speed propeller, and Hartzell 835-47(P) or 835-52(P) spinner.
	<i>PA-31-350</i> SA5796NM SA693CE		Boundary Layer Research Brackett Aero Filters Inc.	Vortex generators IAW Document AA1113. Replace existing engine induction air filter with AC Spark Plug filter.